

twilight

INSTRUMENTOS DE MEDICIÓN INDUSTRIAL

Vacuómetro

VC-9200

www.twilight.mx

 / [twightsadecv](https://www.facebook.com/twightsadecv)

 / [twightsadecv](https://twitter.com/twightsadecv)

 / [twightsadecv](https://www.youtube.com/twightsadecv)

TABLE OF CONTENTS

1. FEATURES.....	1
2. TYPICAL APPLICATION.....	2
3. SPECIFICATIONS.....	2
3-1 General Specifications.....	2
3-2 Electrical Specifications.....	3
4. FRONT PANEL DESCRIPTION.....	4
4-1 Display.....	4
4-2 Power Button.....	4
4-3 Data Hold Button.....	4
4-4 " Max./Min. " Button.....	4
4-5 Unit Button.....	4
4-6 Battery Compartment/Cover.....	4
4-7 Sensor Input Socket.....	4
4-8 RS-232 Output Terminal.....	4
4-9 Port Connector (1/4" NPT).....	4
4-10 Vacuum Sensor Main body.....	4
4-11 Plug of Vacuum Sensor.....	4
4-12 Adapter connector that convert 1/4" NPT to 1/4" PS.....	4
4-13 Port Connector (1/4" PS).....	4
5. MEASURING PROCEDURE.....	5
6. AUTO POWER DISABLE.....	7
7. RS232 PC SERIAL INTERFACE.....	7
8. BATTERY REPLACEMENT.....	9
9. OTHER OPTIONAL ACCESSORIES.....	9

1. FEATURES

- * Absolute vacuum & absolute pressure measurement.
- * Wide measure range from 1 to 1500 mbar.
- * Overload protection up to 2000 mbar max.
- * Separate probe, easy operation.
- * Application : Automobile, Industrial, laboratory, heating, ventilation, medical hospital.....
- * Heavy duty sensor used for air, oil gas, liquid.
- * 8 kind display units (torr, mm Hg, micron, mbar, KPa, Pa, inch Hg, psi) select by push button on the front panel.
- * Auto shut off saves battery life.
- * Microprocessor circuit assures maximum possible accuracy, provides special functions and features,
- * Records maximum & minimum readings with recall.
- * Data Hold function for stored the desired value on display.
- * Built-in low battery indicator.
- * RS232 PC serial interface, can match the personal computer used as the Data Logger, Recorder....

2. TYPICAL APPLICATION

- * Measure pneumatic pressures.
- * Measure automobile engine pressures.
- * Pressure for super heat measurements.
- * Hydraulic servo controls.
- * Refrigeration.
- * Air conditioning.
- * Food processing.

3. SPECIFICATIONS

3-1 General Specifications

Display	61 mm x 34 mm super large LCD display. 15 mm (0.6") digit size.
Display units	8 kind display units : torr, mm Hg, micron, mbar, KPa, Pa, inch Hg, psi.
Circuit Function	Microprocessor LSI circuit. Data hold, memory (max., min.)
Sensor probe	* Separate probe, easy operation. * Heavy duty sensor used for vacuum measurement of air, oil gas, liquid.
Data hold	By push button.
Data record	Record maximum & minimum readings.
Data output	RS 232 PC serial interface.
Sampling time	Approx. 0.8 second.
Power off	Auto shut off, saves battery life, or manual off by push button.
Operating temperature	0 to 50 °C (32 to 122 °F).
Operating humidity	Less than 80% R.H.

1006P DC 9V battery head

Approx. DC 7.1 mA.

1/4" NPT or 1/4" PS

* Included one adapter connector that converts

the 1/4" NPT to 1/4" PS.

Weight	Instrument : 220 g/0.48 LB.
Dimension	Sensor probe 183 /0.4 LB.
	Meter : 180 x 78 x 34 mm (7.1 x 3.1 x 1.4 inch)
Accessories	Sensor probe : 102 mm x 30 mm Dia. 4.02 inch x 1.2 inch Dia.
	* Vacuum sensor probe..... 1 PC. * Instruction manual..... 1 PC.
included	* Hard case in case..... 1 PC.
Optional accessories	* Data acquisition software (Windows version), SW-U801-WIN. * RS232 cable, UPCB-01 * Data logger, DL-9601A. * SD Data logger DL-9602SD.

3-2 Electrical Specifications

Unit	Max. range	Resolution	Accuracy
mbar	1500 mbar	1 mbar	
KPa	150.0 KPa	0.1 KPa	± 1 % F. S.
Pa	150,000 Pa	100 Pa	(23± 5 °C)
torr	1125 torr	1 torr	Note :
mm Hg	1125 mm Hg	1 mm Hg	Included linearity,
micron	1125,000 micron	1000 micron	hysteresis and
inch Hg	44.30 inch Hg	0.02 inch Hg	repeatability
psi	21.75 psi	0.01 psi	F.S.: Full Scale

4. FRONT PANEL DESCRIPTION




Fig. 1

- 4-1 Display
- 4-2 Power Button
- 4-3 Data Hold Button
- 4-4 " Max./Min. " Button
- 4-5 Unit Button
- 4-6 Battery Compartment/
Cover
- 4-7 Sensor Input Socket

- 4-8 RS-232 Output Terminal
- 4-9 Port Connector (1/4" NPT)
- 4-10 Vacuum Sensor Main body
- 4-11 Plug of Vacuum Sensor
- 4-12 Adapter connector that
convert 1/4" NPT to 1/4" PS
- 4-13 Port Connector (1/4" PS)

5. MEASURING PROCEDURE

- 1) Plug the " Plug of Vacuum Sensor " (4-11, Fig. 1) into meter's " Sensor Input Socket " (4-7, Fig. 1).
- 2) Power on the meter by pressing the " Power Button " (4-2, Fig. 1).
- 3) To select different measuring unit by pressing the " Unit Button " (4-5, Fig. 1). There are eight units for your choice.
- 4) Connect the " Port Connector of Vacuum Sensor " (4-9, or 4-13, Fig. 1) to the equipment that intend to be measured the vacuum value.
- 5) Apply the equipment and the vacuum meter will show the vacuum value.

6) Data Hold

During the measurement, pushing the " Data Hold Button " (4-3, Fig. 1) will freeze the measured value on display and there will indicate a " HOLD " symbol.

- * Push the "Data Hold Button" again to exit the data hold function.

7) Data Record (Maximum, Minimum reading)

- * The DATA RECORD function displays the maximum and minimum readings. To start the DATA RECORD function, press the " Max./Min. Button " (4-4, Fig. 1) once. " REC " symbol will appear on the LCD display.
- * With the " REC " symbol on the display :
 - a) Push the " Max./Min. Button " (4-4, Fig. 1) once, the " Max " symbol along with the maximum value will appear on the display.
 - b) Push the " Max./Min. Button " again, the " Min " symbol along with the minimum value will appear on the display.
 - c) To exit the memory record function, push the " Max./Min. " button continuously for around 2 seconds. The display will revert back to the current reading.

8) For quick measurement, follow the procedures shown below

Main procedures :

Connect the " Sensor Plug " to the meter's " Input Socket ".

Power on the meter & select the display unit.

Connect the pressure sensor connector with the equipment.

Apply the equipment and get the pressure value.

Optional measuring procedures :

<u>DATA HOLD</u>	<u>MEMORY RECORD</u> Max., Min.	<u>RS232 OUTPUT</u>
------------------	------------------------------------	---------------------

Power management :

AUTO POWER OFF or MANUAL POWER OFF
(Not available during Memory Record function)

9) Measuring considerations :

- * *The sensor diaphragm can be damaged by solid or sharp objects. Never insert any object into the inlet port.*
- * *The vacuum sensor is compatible with industrial gases & liquid that are compatible with ceramic material. To determine the compatibility of a liquid or gas, refer to manufacture's specification.*

6. AUTO POWER OFF DISABLE

The instrument has built-in " Auto Power Off " in order to prolong battery life. The meter will switch off automatically if no buttons are pressed for around 10 minutes.

To inactivate this feature by pressing the " Max./Min. " button (4-4, fig. 1) to get into the memory record function during the measurement.

7. RS232 PC SERIAL INTERFACE

The instrument features an RS232 output via 3.5 mm Terminal (4-8, Fig. 1).

The connector output is a 16 digit data stream which can be utilized to the user's specific application.

An RS232 lead with the following connection will be required to link the instrument with the PC serial input.



Center Pin.....Pin 2
Ground/shield..... Pin 5

The 16 digit data stream will be displayed in the following format :

D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0


Each digit indicate the following status :

D0	End Word
D1 & D8	Display reading, D1 = LSD, D8 = MSD For example If the display reading is 1234, then D8 to D1 is : 00001234
D9	Decimal Point(DP), position from right to the left 0 = No DP, 1= 1 DP, 2 = 2 DP, 3 = 3 DP
D10	Polarity 0 = Positive 1 = Negative
D11 & D12	Annunciator for Display Psi = 23 mm/Hg = 78 inch/Hg = 80 mbar = 86 Pa = 87 K Pa = 88 u Hg = 89 torr = 90
D13	1
D14	4
D15	Start word

RS232 FORMAT : 9600, N, 8, 1

Baud rate	9600
Parity	No parity
Data bit no.	8 Data bits
Stop bit	1 Stop bit

8. BATTERY REPLACEMENT

- 1) When the left corner of LCD display show "  ", it is necessary to replace the battery. However, in-spec measurement may still be made for several hours after low battery indicator appears before the instrument become inaccurate.
- 2) Slide the " Battery Cover " (4-6, Fig. 1) away from the instrument and remove the battery.
- 3) Install a 9 V battery (heavy duty) and replace the cover.

9. OPTIONAL PRESSURE SENSOR

RS-232 cable, Model : UPCB-01 Application Software (Window version) Model : SW-U801-WIN	RS-232 cable, used for connecting the pressure meter & the computer. After setup whole hardware <i>Pressure meter + RS-232 cable + Computer + software (SW-U801-WIN)</i> whole system can execute as a data logger, data recorder.... record data can be retrieved for EXCEL.....
Data ogger, Model : DL-9601A D Data ogger, Model : DL-9602SD	Rea time ata ogger, a er ogging the data, then it can send out all data to the computer. Innovation an easy operation, computer is not need to setup extra software, after execute datalogger, just take away the S card from the meter and plug in the SD card into the computer, it can down load the measured value with the time information (year/month/date/ hour/minute/second) to the Excel directly then user can make the further data or graphic analysis by themselves.



+52(81) 8115-1400 / +52 (81) 8173-4300

**LADA Sin Costo:
01 800 087 43 75**

**E-mail:
ventas@twilight.mx**

www.twilight.mx

