Medidor de temperatura/Humedad,temperatura de punto de rocío y bulbo húmedo, Sensor Integrado, Datalogger, Tenmars

TM-182

TM-182

Temperature / Humidity Meter (Data logging)

Features:
- LCD display.
- It shows both the value of temperature and humidity.
- Selectable temperature unit of °C or °F.
- Real time data.
- Data Hold function.
- Alarm function.
- Backlit display.
- Auto power off.
- DEW-POINT and WET-BULB temperature.
- USB PC interface.
- Low battery indication "⊟".
- Over load display "OL".
- Humidity accuracy : ±3% RH (20%~80%RH); other ±5%RH.
- Temp accuracy : ±1°C / ±2°F.

Specifications:
- Display : Dual display of LCD, humidity detective capability up to 999, and temperature detective capability up to 1999.
- Temperature sensor : Diode.
- Humidity sensor : Capacitive Sensor.
- Sampling : 1 time / second.
- Power : 9V battery, NEDA 1604, IEC 6F22 or JIS 006P and AC to DC adapter. (9V/300mA).
- Resolution : 0.1%RH, 0.1°C, 0.1°F.
- Data logging capacity : 30,000 data sets.
- Size : 130x56x38mm.（LxWxH）
- Weight : 250g.
- Operating temperature and humidity : -20°C ~ 60°C, <95% RH. (Non-condensing)
- Storage temperature and humidity : -10 to 60°C, <70% RH. (Non-condensing)
- Consumption current : ≦10mA.
- Standard accessories : user's manual, 9V battery, carrying case, mini USB 4P (male) to USB A Type cable and Install CD disk.

twilight

INSTRUMENTOS DE MEDICIÓN INDUSTRIAL

📞 LLÁMANOS

+52(81) 8115-1400 / +52 (81) 8173-4300

LADA Sin Costo:
01 800 087 43 75

E-mail:
ventas@twilight.mx