

# twilight

INSTRUMENTOS DE MEDICIÓN INDUSTRIAL

**Refractometro para Acido  
Acético  
AT-PAL30S**


[www.twilight.mx](http://www.twilight.mx)








# PAL Refractometer

## How to Use



## Error Messages



## Attention

- \*Thoroughly wash and dry after use.
- \*Clean oily residues with alcohol or soap.



INSTRUMENTOS DE MEDICIÓN INDUSTRIAL

 LLÁMANOS

**+52(81) 8115-1400 / +52 (81) 8173-4300**

LADA Sin Costo:  
**01 800 087 43 75**

E-mail:  
**ventas@twilight.mx**

**www.twilight.mx**